

SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC REFRIGERATION SYSTEMS:HOT WATER HEAT PUMP UNIT

Series : CRHV-P·YA-HPB

REVISED

Sept. 2016

BWE01329B



INDEX
CRHV-P600YA-HPB


Part information update day : **2016/09/09**

Please change the old catalog (issued Aug. 2014, No.BWE01329A) to this new catalog.
Content of revision : Some of parts are changed.





Detailed view of section A
(Serial number : 32W00001~57W00175)





*1 After replacing the Heat exchanger assy (202), charge 400cc of Ester oil (401) into each circuit. Refer to the Service hand book (No.HWE13120) for details.





mitsubishi
electric
corporation

BWE01329B (20160930)